WORKPLACE SAFETY CARD



Cavex ImpreSafe

Inside low risk

Physical state: Liquid. Color: Colorless to light yellow.

Most important hazards:

R21/22- Harmful in contact with skin and if swallowed.

R34- Causes burns.

R50/53- Very toxic to aquatic organisms, may cause long-term adverse effects in the aquatic environment.

Contains: 25 - 30 % Alkylbenzyldimethylammoniunchloride. C; R34, Xn;R21/22, N;R50/54. CAS number 68391-01-5.

Hazard symbol or symbols:



Protective measures

Protective measures

Fire/explosion Extinguishing media

Not applicable.

Use extinguishing media suitable for surrounding

INHALATION First aid measures

Not applicable.

INGESTION

Pure product.

Have conscious person drink several glasses of water or milk. Get medical attention immediately.

Aqueous, ready for use solution.

Have conscious person drink several glasses of water or milk. Get medical attention/advice if you feel unwell.

S24- Avoid contact with skin. Wear suitable gloves. Nitrile gloves.

$\underline{SKIN\ CONTACT} \ \text{Pure product}.$



After contact with skin, take off immediately all contaminated clothing, and wash immediately with plenty of soap and water.Get medical attention if irritation develops.

Aqueous, ready for use solution.

Take off immediately all contaminated clothing. Wash contaminated skin with plenty of water. Get medical attention if irritation develops.

S25- Avoid contact with eyes. Nitrile gloves.

EYE CONTACT Flush with plenty of water for at least 15 minutes,



occasionally lifting the upper and lower eyelids. Get medical attention as soon as possible and show this card to the medical personnel.

Methods of disposal: Pure product should be regarded as hazardous waste.

Aqueous, ready for use solutions should be reagarded as non hazardous.

Storage: No specific storage is required.

Other information:

Version number: WSC Number: Date: 18-2-2010.